# Citizens Weather Observing Program (CWOP) Configuration for *Davis Weather Link (PC)* Users

(Last updated: 10 July 2012)

#### 1.) Gather Station Location Data


- You will need your Latitude and Longitude in degrees/minutes/seconds format, and Elevation in metres.
- See the How-To "Signing up for CWOP" for methods to obtain your station location data:

www.srh.noaa.gov/media/epz/mesonet/CWOP-SignUp.pdf

#### 2.) Get a CWOP Station ID:

With any web browser, fill out the form at: <a href="http://www.findu.com/citizenweather/cw">http://www.findu.com/citizenweather/cw</a> form.html

The CWOP website is a little "old-fashioned" and unpolished, and it contains far more information than the average user needs. Don't worry about the parts of the form mentioning "Packet Checking" and "MADIS tech support."



- Make sure you use a valid email address (don't worry no SPAM).
- If you are a business or agency, you may wish to use its name in place of "First Name" and "Last Name." Otherwise, use whoever will be the primary contact.
- If you need help with any of these steps, or finding your location or elevation, send an email to: *mike.hardiman@noaa.gov*.

#### 2.) Send the form, then make note of your CWOP Station ID:


Your Citizen's Weather Account Number is: DWxxxx

An email will be sent to John Doe (johndoe@anonymous.net) confirming this number.

#### 3.) Configure Weather Link Internet Settings:

- This assumes you've already setup your Weather Link software to work with your weather station.
- Click on the Setup Menu, then select Internet Settings.
- In the Internet Settings dialog box, in the Data
  Upload Summary section, click the Configure
  Button associated with an unused profile.
- You may already have some profiles in use for uploads to other sites such as the Weather Underground, or a custom personal web page.








- In the **Data Upload Profile** window, set the Upload Frequency to **5 min** and the **Starting At** time to any time. (It is suggested you pick an off-minute like :03 or :07 rather than a round :05).
- Next, click the **Select Report Files** button.

 On the Upload Weather Reports for Data Upload Profile window, click on the Configure button in the APRS Weather Report section.

- On the APRS Setup Window, enter your CWOP Station ID under the Call Sign section.
   Leave the Telnet section set to the default.
- Click the **Modify** button in the **Location** section.
- If you have your station location in Decimal Degrees, you'll need to convert it to Degrees/Minutes/Seconds.
- You can quickly convert your location coordinates using this web site:







http://transition.fcc.gov/mb/audio/bickel/DDDMMSS-decimal.html/

- On the conversion webpage, enter your decimal Latitude and Longitude in the pink box, then click **Convert**.
- Make note of the results, ignoring the decimal seconds.
- Decimal Degrees to Degrees Minutes Seconds

  Enter Decimal Latitude:

  Enter Decimal Longitude:

  Convert to Degrees Minutes Seconds

  Clear Values

  Results: Latitude: 31° 52' 8.3994"

  Longitude: -106° 38' 56.4"

Set Latitude & Longitude


- So in this example, make note of 31° 52′ 08″ and -106° 38′ 56″.
- Back in the **Set Latitutude & Longitude** window, enter your converted coordinates. Leave out the "-" sign in the longitude. Select "North" for Latitude, and "West" for Longitude, assuming you're in North America. Click **OK**.
- Latitude


  Deg 52 Min 7 Sec North South

  Longitude


  106 Deg 38 Min 55 Sec East West

  OK Cancel Help
- Then Click **OK** in the **APRS Setup** window.
- Then in the **Upload Weather Reports** window, in the **APRS Weather Report** section, click on the **On** button. Then click **OK**.
- Back in the Data Upload Profile window, click on OK.
- Back in the **Internet Settings** window, click the button next to **Internet Transfer Enabled** so it reads, "**On**".
- Next, click on the Internet
   Connection Settings button.






• In the Internet Connection Settings window, click on the Internet Transfer Enabled checkbox in the bottom-left corner, then click OK.



• Finally, back in the **Internet Settings** window, click on "**OK**."



#### 4.) Check for Data:

- Browse to the following web address, using your CWOP Station ID at the end: http://www.findu.com/cgi-bin/wx.cgi?call=YOUR CWOP ID HERE
- For example, if your Station ID was CW0958, you would enter: http://www.findu.com/cgi-bin/wx.cgi?call=CW0958

Note: It may take up to 10 minutes for data to start appearing.

**Also Note:** The date/time stamp used on the above site is in the form YYYYMMDDhhmmss in UTC time. For example "20120402145210" means April 2, 2012 at 14:52 UTC (+10 sec).

### 5.) Let us know you're online!

- You should receive an email from CWOP asking you to check your station location and make sure your data is flowing.
- If you are in Southern New Mexico or West Texas, you may send an email to mike.hardiman@noaa.gov. We'll make sure everything looks good with your data, and ensure it is added to various data feeds.
- Otherwise, respond to the email from CWOP.

## 6.) MesoWest/MADIS Updates:

• These two data aggregators usually update their station tables on a weekly basis (usually Wednesdays). After several days, data from your station should begin showing up on plots at MesoWest:

http://mesowest.utah.edu/cgi-bin/droman/mesomap.cgi?state=NM&rawsflag=3